

b)

OR

5

5

6

5

6

- An iron, ring of 8 cm mean diameter is made up of round iron of diameter 1 cm and a) permeability of 900, has an air gap of 2 mm wide. It consist of winding with 400 turns carrying a current of 3.5 A. Calculate : **Total Reluctance** i) MMF ii) iii) The flux Flux density in the ring iv) b) Define : **Residual flux** i) ii) Co-ercive force Similarities of electric & magnetic circuit. iii) Explain the phenomenon of electrical resonance in series a.c. circuits. Derive the a) expression for resonant frequency. b) A coil takes 10 A from 200V, 50 Hz supply It's resistance is 5 Ω . Determine it's Inductance Real power in kw i) ii) iii) Reactive power in kVAR Impedance iv) v) Apparent power in kVA vi) Phasor dig.
- 6. a) Prove that a 3 phase balanced load draws three times as much power when connected in Delta, as it would draw when connected in STAR.
 - b) Three identical coil's of $(9+j12)\Omega$ are connected in delta to a 400V, 50 Hz, 3 ϕ AC supply. Calculate for this load.

OR

- i) Line current iii) $\cos \phi$ iv) kvA
 - v) kw
- 7. a) Why does a transformer is said to be a constant flux machine.
 - b) A 400/200 V, 1φ transformer is supplying load of 50 A at the power factor fo 0.866 lagging. The no load current is found to be 2A at 0.208 power factor lagging. Calculate the current & power factor on primary side of transformer.

OR

8. a) Explain O.C. and S.C. test on single phase transformer with circuit diagram.

- The iron and full load copper loss in a 40 kvA single phase transformer are 250 w and 750 w respectively. Calculate :
- i) Efficiency at 50% of full load 0.8 p.f. leading
- ii) Load at which the efficiency is maximum.

KNT/KW/16/7199

b)