Faculty of Engineering & Technology Fourth Semester B.E.(Aeronautical Engineering) (C.B.S) Examination AIRCRAFT MATERIALS

Time—Three Hours]

[Maximum Marks—80

INSTRUCTIONS TO CANDIDATES

- (1) All questions carry marks as indicated.
- (2) Solve Q.1 or Q.2, Q.3 or Q.4, Q.5 or Q.6, Q.7 or Q.8, Q.9 or Q.10, Q.11 or Q.12.
- (3) Due credit will be given to neatness and adequate dimensions.
- (4) Assume suitable data wherever necessary.
- (5) Illustrate your answers wherever necessary with the help of neat sketches.
- (6) Discuss the reaction, mechanism wherever necessary.
- (7) Use of Non-programmable calculater is permitted.
- 1. (a) What are the properties of Engineering Materials?

 Explain it with examples in detail.
 - (b) Explain the use of aluminium in Aircraft Construction.

6

OR

2. (a) Discuss the influence of adding following alloying elements on properties of steel:

		(i) Chromium	
		(ii) Vanadium	
		(iii) Molybdenum.	6
	(b)	Are the heat treatment procedures same for st and aluminium alloys? If yes, justify your answ	eel ver. 7
3.	(a)	What are Composite Materials? Write its advanta	ges
		and disadvantages.	7
	(b)	Describe about 'Fiber Orientation'.	6
		OR	
4.	(a)	Write properties, application and the fabrication	of
		glass fibres.	8
	(b)	Compare composite with Metals.	5
5.	(a)	Write in brief about PMC's.	8
	(b)	Explain about compression molding.	6
		OR	
6.	(a)	Are pre-impregnated materials called as prepreg	gs?
	,	If yes, what are prepregs? Explain about	its
		manufacturing procedure.	8

(b) Explain with diagram "Hand lay-up method".

2

MIN--5386

7.	(a)	Define Creep. Explain the mechanism of Creep. 8		
	(b)	Explain with the help of graphs the transient and viscous creep. 5		
		OR		
8.	(a)	Write a note on "Low temperature and High temperature creep".		
	(b)	Describe about "Deformation at Elevated Temperatures."		

A sample of glass has a crack of half length $2\mu m$. The Young's modulus of glass is 70 GNm⁻² and the specific surface energy is 1 Jm⁻². Estimate its fracture strength and compare it with its Young's modulus.

(a) Explain and plot the typical graphs for stress amplitude versus number of cycles for steel and aluminium alloy,

OR

Distinguish between "Ductile and Brittle fracture". 6

(b) Write a short note on "factors affecting fatigue 7 properties" of a material.

11. (a) What are superalloys ? Give their composition, properties and application of superalloys. 7

3

Contd.

MLV---5386

Contd.

(b)	What are high	temperature	ceramics? Explain.	7
		ΩP		

- 12. (a) Illustrate with an example solid solution strengthening.
 - (b) Write a note on "Nickel Base Superalloys".

5